



REPORT OF ANNUAL INSPECTION OF CCR LANDFILL	
CCR LANDFILL NAME: Plant Crist Ash Landfill 1	
OWNER OF CCR LANDFILL: NextEra - Gulf Power	
INSPECTION DATE: November 19, 2019	
INSPECTING ENGINEER: Kevin S. Brown, P.E. FL PE 57819	
APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE TIME OF INSPECTION (CU. YDS.)	4,063,428
ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?	NO
(IF YES, DESCRIBE):	
ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT OR APPURTENANT STRUCTURES?	NO
(IF YES, DESCRIBE):	
ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION?	NO
(IF YES, DESCRIBE):	
WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE PREVIOUS ANNUAL INSPECTION COMPLETED?	N/A
(IF NO, DESCRIBE): There were no corrective actions identified in the previous Annual Inspection	

<p>Based on the results of my inspection and review of the data provided, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.84(b).</p> <p style="text-align: center;">  1/23/2020 </p> <hr style="width: 80%; margin-left: 0;"/> <p>Kevin S. Brown, P.E. Date</p>	
---	--