REPORT OF ANNUAL INSPECTION OF CCR LANDFILL	
CCR LANDFILL NAME: Plant Crist Ash Landfill 2	
OWNER OF CCR LANDFILL: Gulf Power Company	
INSPECTION DATE: November 19, 2018 2019 Revised by Kevin Brown to correct Year, 2/21/2022	
INSPECTING ENGINEER: Kevin S. Brown, P.E. FL PE 57819	K=3
APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT	292,231
THE TIME OF INSPECTION (CU. YDS.)	
ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE	NO
PREVIOUS ANNUAL INSPECTION?	NO
(IF YES, DESCRIBE):	
ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL	
WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS	
THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT	NO
THE OPERATION AND SAFETY OF THE CCR UNIT OR	
APPURTENANT STRUCTURES?	
(IF YES, DESCRIBE):	
ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE	
STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL	NO
INSPECTION?	
(IF YES, DESCRIBE):	
WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE	N/A
PREVIOUS ANNUAL INSPECTION COMPLETED?	
(IF NO, DESCRIBE): There were no corrective actions identified in the previous Annual Inspection	